

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: Riley et al. Attorney Docket No. BIOL0080
 Patent No: 7,006,710 Group Art Unit: 2621
 Issued: February 28, 2006 Examiner: Alavi, Amir
 Title: METHOD AND APPARATUS FOR CORRECTING CROSSTALK AND
 SPATIAL RESOLUTION FOR MULTICHANNEL IMAGING
NOTIFICATION OF ERRORS

Bellevue, Washington 98004

August 2, 2006

TO THE COMMISSIONER FOR PATENTS:

The following errors were found during a review of the above-referenced United States Letters Patent. These errors were either inadvertently made in the original application or occurred in the printing of the patent. Since the errors are of an obvious nature, a formal Certificate of Correction is not believed to be warranted at this time. Therefore, it is requested that this notification be placed in the U.S. Patent and Trademark Office file.

Location in PatentError

FIGURE 9

"FREQUENCY" should read --FREQUENCY--

Column 19, line 20
 (Equation 24)

$$A = U \cdot \vec{D} V \quad \text{should read} \quad A = U^T \vec{D} V$$

Column 19, line 21

"U₁" should read --U¹--

Column 19, line 55
 (Equation 26)

$$= V^T \vec{D}^{-1} U \vec{M} \quad \text{should read} \quad = V^T \vec{D}^{-1} U \vec{M} \quad --$$

Column 20, line 66

"S_n" should read --s_n--

Respectfully submitted,

/mike king/

Michael C. King

Registration No. 44,832